



TEST REPORT



1. NO : CT21-037481E
2. Client
 - Name : HYUNDAI L&C
 - Address : 26, Eulji-ro 5-gil, Jung-gu, Seoul, 04539 Republic of KOREA
3. Date of Test : 2021.03.24 ~ 2021.04.02
4. Use of Report : Quality Control
5. Test Sample : DELUXE TILE 3T(300x300)
6. Test Method
 - (1) KS M 1991:2016

Affirmation	Tested By Name : Noh Incheol		Technical Manager Name : Bae Sangbok	
-------------	---------------------------------	--	-----------------------------------------	--

This report is accredited by KOLAS.
 Our report apply only to the standards or procedures identified and to the sample(s) tested unless otherwise specified. The test results are not indicative of representative of the qualities of the lot from which the sample was taken or of apparently identical or similar products. The results of using only a portion of this report cannot be guaranteed. The authenticity of this test report can be checked on KCL website(www.kcl.re.kr).

The above test certificate is the accredited test results by Korea Laboratory Accreditation Scheme, which signed the ILAC-MRA.

2021.04.02

Korea Conformity Laboratories President Yoon, Kap Seok

Accredited by KOLAS, Republic of KOREA

Result Inquiry : 199, Gasan digital 1-ro, Geumcheon-gu, Seoul, Korea 82-2-2102-2676



TEST REPORT



No : CT21-037481E

7. Test Results


1) DELUXE TILE 3T(300x300)

Test Item(s)	Unit	Test Method	Test Results	Remark	Loc.
Dibutylphthalate(DBP)	mg/kg	(1)	Not detected (detection limit 50)		A
Butylbenzylphthalate(BBP)	mg/kg	(1)	Not detected (detection limit 50)		
Di-(2-ethylhexyl)phthalate(DEHP)	mg/kg	(1)	Not detected (detection limit 50)		
Di-n-octylphthalate(DNOP)	mg/kg	(1)	Not detected (detection limit 50)		
Di-(iso-nonyl)phthalate(DINP)	mg/kg	(1)	Not detected (detection limit 50)		
Diisodecylphthalate(DIDP)	mg/kg	(1)	Not detected (detection limit 50)		

※ Location

A : 199, Gasan digital 1-ro, Geumcheon-gu, Seoul, Korea

----- End of Report -----



복사본 COPY
COPY 복사본

